Radiogram No. 9991u Form 24 на 03/17/05 **MO-6. ПхО and DC1 Set up for EVA**

GMT	CREW	ACTIVITY
06:00-06:10		Morning inspection
06:10-06:40		Post-sleep
06:40-07:30		BREAKFAST
07:30-07:45		Daily planning conference (S-band)
07:45-09:45		ПхО and DC1 set up for EVA
09:50-09:55	CDR	HAM radio set up
09:55-10:25	FE-1 CDR (assist)	Hand ergometry To=10:04 Tagup w/specialists (VHF)
10:25-11:25	FE-1	SM panel 101 photo/file prep for downlink via OCA
10:25-10:35	CDR	HAM radio pass
10:35-10:50	CDR	Food frequency questionnaire
11:05-11:25	CDR	IMS file prep
11:30-12:00	CDR FE-1 (assist)	Hand ergometry To=11:37 Tagup w/specialists (VHF)
12:00-12:15	FE-1	IMS tagup (S-band)
12:00-12:15	CDR	Routine inspection of RED
12:15-13:45	FE-1	Physical Exercise (TVIS) day 1
12:15-13:45	CDR	Physical Exercise (RED)
13:45-14:05	FE-1	Condensate sampling (KAB) upstream of Purification column unit (БКО) in condensate water recovery system [CPB-K2M]: system set up, sampler installation
13:45-13:55	CDR	CSA-CP data collection
14:05-15:05		LUNCH
15:05-16:05	CDR	US EVA tool prep
15:25-15:35	FE-1	KAB sampling upstream of БКО CPB-K2M: sampler changeout
15:35-15:55	FE-1	PLANTS-2. Data downlink
16:05-16:50	CDR	Monthly maintenance of TVIS
16:05-17:05	FE-1	Physical Exercise (VELO + Force Loader/cycle) day 1
16:50-17:50	CDR	Physical Exercise (TVIS)
17:05-17:20	FE-1	KAB sampling upstream of БКО CPB-K2M: sampler removal
17:20-18:20	FE-1	Water sampling from water distribution and heating unit (БРП-М) into sample container (ЕДП) from HOT tap (without flush) Water sampling from БРП-М into drink bags
17:50-17:55	CDR	TVIS/RED/HRM data transfer to MEC
17:55-18:25	CDR	СОЖ maintenance
18:20-18:40	FE-1	Daily plan review
18:30-18:45	CDR	Daily plan review
18:40-18:45	FE-1	STATOKONIA. Temperature check per [APT]
18:45-19:00		Daily planning conference (S-band)
19:00-19:30		Report prep
19:30-20:00		Daily ration prep
20:00-20:30		DINNER
20:30-21:30		Pre-sleep

21:30-06:00		SLEEP
Task List	FE-1	PLANTS-2. Water container top-off
		Audit of equipment to record ACH-M data to Laptop 3
		ССВП wipes audit in Soyuz БО
		ТБУ. Temperature check

Note: See OSTP for references to US hardware

End of radiogram